

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
AK,  
6-CHAT.V,  
1-

Davidson Ditch Waste Weir  
Mile 63 of Alaska's Steese Highway  
Fairbanks County

HAER No. AK-5

Laurence A. Peterson, Photographer, October 1, 1979.

- AK-5-1      PHOTOGRAPH TAKEN FROM THE SOUTH LOOKING NORTH ACROSS AN ERODED AREA. THE SOUTH END OF THE FLUME HAS COLLAPSED.
- AK-5-2      PHOTOGRAPH TAKEN FROM NORTH SIDE OF DAVIDSON DITCH LOOKING SOUTH ALONG LENGTH OF FLUME--VEGETATION NOT REMOVED AS PER ALASKA DEPARTMENT OF TRANSPORTATION PERSONNEL.
- AK-5-3      PHOTOGRAPH TAKEN FROM WITHIN THE FLUME (MID-POINT) LOOKING NORTH INTO THE DITCH.
- AK-5-4      PHOTOGRAPH TAKEN FROM EAST SIDE OF FLUME LOOKING NORTH TOWARD THE DITCH.